


Boulder Reservoir: Completed Projects



Consultant Data Collection & Analysis

- 2012 Visitor Data & Surveys
- 2012 Environmental Overview (ERO)
- 2012-2014 Traffic Study (Fox/Tuttle)
- 2013 Visitor Data
- 2013 Environmental Assessment (Biohabitats)
- 2014 Small Mammal Survey (Wildlife Specialties)

Feeder Canal Bridge & Overlook Improvements

Two photographs showing the Feeder Canal Bridge & Overlook Improvements. The left photo shows a bridge over a canal, and the right photo shows a gravel overlook area with large stone blocks.

North Shore Trail Improvements

Two photographs showing the North Shore Trail Improvements. The left photo shows workers clearing a trail, and the right photo shows workers planting trees along a trail.

South Shore Infrastructure Improvements

Three photographs showing the South Shore Infrastructure Improvements. The top left photo shows a gate structure, the top right photo shows a paved road with landscaping, and the bottom photo shows a new building and a large blue pipe installation.

